



M02



Pin Assignment

PIN NO.	SIGNAL NAME
1	INPUT +
2	IN COM
3	INPUT -
4	FB
9	N.C.
10	N.C.
11	PWR +15V
12	PWR COM.
13	OUTPUT -
14	OUTPUT +
15	N.C.
16	N.C.
21	IN COM.
22	IN COM.
23	EX +
24	EX -

Pin Location(Top View)



単位:mm